

Performa For This Safety Certificate Of School Building

1. Name the school D.M. Public Sen Sec. School

2. Location Situated at Po- Kasar Wala.

3. Plot area 12144.98 Sq. Mt

4. Plinth area 1768.48 Sq. Mt.

5. No. of stories Two

6. Year of construction 2006-07

7. Whether the building has been constructed under the supervision of the qualified Engineer, If so.

a) Name of the engineer with qualification Harwinder Singh

b) Address Beetaw Arch. near Prod. office Rampura.

c) Set Of structural drawing used in construction

8. Whether the building has been construction for the purpose of:

a) School (Yes/No)

b) Residentail purpose (Yes/No)

c) Converted for school (Yes/No)

9. Material used for roofs :-

a) R.C.C.Slab (Yes/No)

b) R.S joints & Battens (Yes/No)

c) Wooden joits & Battens (Yes/No)

10. Material used for walls :-

a) Mud mortar (Yes/No)

b) Cement mortar (Yes/No)

c) Plaster : line mortal (Yes/No)

Cement mortal (Yes/No)

11. Flooring:-

a) Conglomerate (Yes/No)

b) Terrazo (Yes/No)

c) Brick paving (Yes/No)



12. A detailed drawing indicating demensions of the room & location of doors and windows is attached

13. General

1) in case of double story building 1.5 meter: (yes /No)

Width upstairs are constructed or not

2) Whether all class room are provided two door system (Yes/ No)

3) whwther fire safety measures have been (yes/ No)

Adopted and are in working condition

Principal
D.M.Public Sr. Sec. School
Katturpala (Sti.)
Registration No. 1630965

Dated :

(for the use of

department)

- a) I..... JAGGA SINGH CHAUHAN..... S.D.O. along with
Gour Jugal Singh..... J.E. have visited this school on
30/05/22 and have inspected it from all angles of
safety and found it fit for normal use as school building .
- b) In case any addition alteration , extension or modification of this building is
to be carried out ,it should be carried out under the supervision of technical
qualified engineer ,and after its completion ,this certificates may again be
obtained from the undersigned.
- c) In case the building is affected by flood or if there is settlement to walls
foundations ,edging or roof,immediate inspection of the undersigned be
arranged to check the stability and safety of the building 31-03-23
- d) The building can be safely occupied for normal use up to

Sub-Divisional Officer,
Panchayat Raj, P.W.
SAMPURA